

Construction Update: Iron Horse Trail Overcrossing

Upcoming Changes to Bollinger Canyon Road Traffic



Work continues on the Iron Horse Trail Overcrossing at Bollinger Canyon Road. Please see below for anticipated upcoming work and impacts to traffic flow.

Work Completed Through 1/10/24:

- Completed CIDH (cast in drilled hole) pile work on the North and South Trail
- Completed traffic signal switchover to temporary system
- Completed equipment mobilization to the median
- Completed median CIDH pile work
- Completed traffic signal switchover to the permanent traffic signal system at the intersection of Bollinger Canyon Road and Bishop Ranch 1 East (BR1E)
- Completed adjustment to k-rail to reduce the existing closure area to the original configuration

Work Anticipated Through 1/18/24 (Weather Dependent):

- Continue demolition and excavation on the Iron Horse Trail
- Continue abutment and MSE wall work on the Trail including rebar installation, concrete pours, and panel installation
- Continue pier formation
- Continue utility work on the Iron Horse Trail